

0



May 15, 2012

Correspondence No. 00407

CERTIFIED MAIL 7009 2820 0001 0758 9071

Massaro Construction Management Services 120 Delta Drive Pittsburgh, PA 15238

Attn: Mr. Steve F. Peterman

RE: NEW PIVIK ELEMENTARY SCHOOL

SUBJECT: EXECUTED CHANGE ORDER NO. 019

Dear Mr. Peterman:

Enclosed please find three (3) copies of executed Change Order No. 019.

In an effort to keep the project moving, be advised that Nello Construction signs this Change Order with the understanding that it has reserved all rights under the contract conditions to claim for time extensions and other impacts as becomes necessary, resulting from these changes in scope,

Should you have any questions, please feel free to contact our office.

Respectfully,


NELLO CONSTRUCTION COMPANY

George D. Leasure

President

Enclosures

cc: John Fusco / Nello





Change Order - Construction Manager-Adviser Edition

PROJECT (Name and address): Plum Borough School Reconfiguration 900 Elicker Road Plum, Pennsylvania 15239	CHANGE ORDER NUMBER: 019 INITIATION DATE: 04/25/12	OWNER: ⊠ CONSTRUCTION MANAGER: ⊠ ARCHITECT: ⊠ CONTRACTOR: ⊠
TO CONTRACTOR (Name and address): Nello Construction	PROJECT NUMBERS: CM09-711 /	FIELD:
100 Houston Square, Suite 200 Canonsburg, PA 15317	CONTRACT DATE: 04/12/2011 CONTRACT FOR: General Construction	On in ()
THE CONTRACT IS CHANGED AS FOLLO	WS:	
Relocation of 2 exterior hose bibs, one at Re RFI 073.	com B112 and one at D108. This Chang	ge Order was generated due to the response to
The original Contract Sum was Net change by previously authorized Chang The Contract Sum prior to this Change Ord The Contract Sum will be increased by this The new Contract Sum including this Change	er was Change Order in the amount of	\$ 14,096,400.00 \$ 291,981.26 \$ 14,388,381.26 \$ 2,293.34 \$ 14,390,674.60
The Contract Time will be increased by Zer The date of Substantial Completion as of the	ro (0) days. e date of this Change Order therefore is	
NOTE: This summary does not reflect change authorized by Construction Change Directive	ges in the Contract Sum, Contract Time over.	or Guaranteed Maximum Price which have been
NOT VALID UNTIL SIGNED BY THE OWN	ER, CONSTRUCTION MANAGER, ARCHI	TECT AND CONTRACTOR.
Massao Construction Management Services CONSTRUCTION MANAGER (Firm name) 120 Delta Drive, Pittsburgh, PA 15238 ADDRESS	ARCHITECT Frick Buildi	imball & Associates (Firm name) ng North Mezzanine treet, Piltsbyrgh, PA 15222
BY (Signature) Steven F. Peterman (Typed name) DATE:	BY (Signatu George Kiek (Typed nam	Szek (5/3/12
Nello Construction CONTRACTOR (Firm name) 100 Houston Square, Sulte 200, Canonsbur ADDRESS	OWNER (FI)	igh School District em name) Road, Plum, PA 15239
BY (Signature) George D. Leisure (Typed name) DATE:	4 • 12 BY (Signatu Timothy Gl (Typed nam	asspool, Superintendent

NELLO CONSTRUCTION 60TH ANNIVERSARY

PROPOSED CHANGE ORDER No. 00036

CORRESPONDENCE NO: 00385

ARCHITECT PROJECT NO: 09-2200-05

100 Houston Square Suite 200 Cananainum 15317

Canonsburg, 15317

Phone: 724-746-1900 Fax: 724-746-7032

TITLE: Relocate Wall Hydrants

DATE: 4/2/2012

PROJECT: NEW PIVIK ELEMENTARY SCHOOL

GC PROJECT NO:1724

TO:

Massaro CM Services LLC

120 Delta Drive

Pittsburgh, PA 15238-2806

Phone: 412-963-2800

Fax: 412-599-0039

Attn: Steve Peterman

DESCRIPTION OF PROPOSAL.

We are requesting an ADD to our Contract Sum of \$2,293.34 to relocate the wall hydrants at Rooms B112 and D108 per RFH/073.

This proposal excludes any OCIP deductible in the event that an incident may occur related to this work.

We reserve our right to claim additional contract time and cost related to this additional Work, as this Work may impact the schedule and that impact may only be assessed after the completion of the Work and the cumulative consequence of all impacts.

This proposal may be withdrawn if not approved within 30 days.

Piease feel free to contact me if you have any question or require any additional information.

				Mark	CHIP	
Item.	Description	Quantity Units	Unit Price	Rate	Ainmint .	Net Amount
00001	Fush all labor, material, equipment and supervision accessary to reincate the wall hydrants at Rooms B112 and D108 as noted in the response to RFE#073.	1.000 L.S.	\$1,989,00	10.00%	\$198,90	\$2,187.90
00002	Layont and coordination	1.000 Houir	\$45.00	10.00%	· \$4,50	\$49.50
			S	ubtotal:		\$2,237.40
			Во	nd Cost		\$55.94
This request has been reviewed for validity, quantity and pricing and has been found to be reasonable.		· To	otal Cost:		\$2,293,34	
			Signed:	~		
					John Fu	SCO



A. J. Demor & Sons, Inc.

Mechanical Contractors

2150 Eldo Road, Monroeville, PA 18148 · Phone: 412-242-8126 · Fex: 412-372-5818 One Line Street, Store #3, Throop, PA 18612 · Phone: 670-383-3878 · Fex: 870-393-3877 Website: www.ajdemor.com

	EXTRA WORK ORD	ERNO.01		
100 Hou	nstruction Company ston Square, Suite 200 urg, PA 15317	NRATI	OCONSTRUCTIC)A :
ATTA	: Mr. John Fusco		0 49 VIII.	'!V
PROJECT	: New Plvlk Elementary School		AECEIVED	
AJD PROJECT	# 2676			
The attached b	eakdown is the estimated cost re	equired to perform	the following proposed e	xtra work;
Relocate wall hydrar October 21, 2011. A installed at these loc	ts in rooms B112 and D108 to new dditional time is required for installa	location as indicate ation of these wall hy	d in RFI #073 response da /drants as a result of brick	ied already
exclusions:				
Jpon acceptance of o our contract in the	the proposed changes per the alta- amount of:	ched Information, we	hereby request an ADD/E	EDUCT
PRICE: One thou	sand nine hundred eighty-nine and	00/100	And and the second like he section that the second	00.088,1
This change proposi We reserve the right as they become kno	nt covers only the direct costs assoc to assess the impact of this change wn.	ciated with the chang e order at a later dal	ge order work described at te and to submit these cost	oove. s
This proposal is for a An extension time of	oceptance within <u>30</u> days and is su <u>0</u> working days is required.	ibject to ascalation t	hereafter.	
Please advise as co	on as possible if we are to proceed.			
Sincerely, A.J. Demor & Sons,	ino.	Accepted by	y:	The state of the s
· (C), MONT TIND Bryan J. Demor Project Manager	mar	D	ate:	
i e mlatare extenseribless				

A STATE OF THE STA	RA WORK ORDER	RECAP		***************************************	
PROJECT. New Pivik Elementary School EWO #010	and the state of t		DATE: AJD PROJ	Nove ECT#	mber 28, 2011 2676
MATERIAL	\$ 306.82	1 1 1 1 1 1 1 1			
EQUIPMENT (Tax Exempt)	\$			(
FREIGHT, OTHER DELIVERY CHARGES	\$				
	THE PERSON NAMED IN THE PE	CONTRACTOR OF THE PROPERTY OF	JULIE DE LA SELECTION DE LA CIDA		
SUBTOTAL MATERIAL & EQUIPMEN	T	\$	308,82		
STATE SALES AND USE TAX @ 7%	The second secon	\$	21.48		
TOTAL MATERIAL AND EQUIPMENT	WITH TAX	\$	328,30		
· · · · · · · · · · · · · · · · · · ·					
LABOR COSTS SUMMARY		\$	1,156.88	1	
EQUIPMENT RENTAL		\$	pæ		
OTHER DIRECT COSTS		\$	***	3 7	
SUBCONTRACTS Insulation		\$	240.00		
And the state of t	and beyonding all proper from the contract of			1	
SUBTOTAL	STATE OF THE PARTY	\$	1,725.18		
% PROJECT OVERHEAD		\$	7		
15% % CORPORATE OVERHEAD (LI	ESS SUBCONTRACTS)	\$	222.78		
5% % CORPORATE OVERHEAD (S	UBCONTRACTS ONLY)	\$	12.00		
- '					
	and the second s	8	UBTOTAL:	\$	1,959.96
The state of the s	Processing the same letter than the same same same same same same same sam	PROFIT:	0.000%	\$	
A STATE OF THE STA		8	UBTOTAL:	Si .	1,959.96
	7557	BOND;	1.500%	\$	29.40
· · · · · · · · · · · · · · · · · · ·		B&O TAX:	0.000%	\$	ę
	· · · · · · · · · · · · · · · · · · ·		************		
	PF-PF-SP-TyPYMByANFRANGERIAN JUMPA	тот	AL PRICE:	\$	1,989,36
MARKET CAREFORD CONTROL OF THE CONTR			· Allende - I de la la la company de la comp		WORLD PROPERTY AND A CO.
The state of the s		F	ROUNDED:	\$	1,989,00

.

:

The first of the second	LA	BOR CO	sts summ	ARY			
PROJECT New Plvik Elementan EWO # 010	/ School	·			DATE: AJD PROJ		er 28, 2011 2675
	***************************************	#Hrs.	Straight	Shift	1 1/2	2	TOTAL
GENERAL FOREMAN	J		11-11-11-11-11-11-11-11-11-11-11-11-11-				\$ -
FOREMAN		8	\$ 72,15	· · · · · · · · · · · · · · · · · · ·			\$ 677.20
SUBFOREMAN	**************************************			· · · · · · · · · · · · · · · · · · ·			\$ -
JOURNEYMAN		8	\$ 63,00	irilai attat liin yalkii aaaa iro			\$ 504.00
LABORER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Primapana			\$ -
TRUCK DRIVER	***************************************						18 -
				тот	AL DIRECT	LABORE	₹: \$ 1,081.20
•		TOO	DL REPLACEN				<u> </u>
							Y \$ 1,156.88

I I EN	NIZED MA	TERIAL &	LAE	3OR	• • • • • • • • • • • • • • • • • • • •	
DESCRIPTION - Material	QTY.	'UNIT \$	7	TOTAL \$	LABOR UNIT	TOTAL
Refer to Attached Breakdown			 		UNII	M/H
ALEL TO WYSTALLON THE STATE OF	<u> </u>	\$ 306,82	\$	306,82		
المراجعة المصطاعة والمرمان منتجر إمناه المعاملة القرميس ويجهو والوسان المراجعة المراجعة والمسادر المراجعة المرا			\$	~		
NI 1960 (Second Lambert 1977) 1967	ira (Pre 17) benida nakali dak aba.		\$	ps.		
			\$	H		
			\$	=		
			\$			PP-V
			T 8	**************************************		
The state of the s	*** Wignes	Name of the State of	\$	H.		the state of the s
			18	73-14-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	***************************************	
		ARTEST STATES OF THE STATES OF	1			Alegaries and harrist holy by an art of the same of th
		**	8		<u> </u>	
DESCRIPTION - Equipment	**		<u>μ</u>		<u>. </u>	· · · · · · · · · · · · · · · · · · ·
			16	** ***********************************		
			18			
			18	ц.		···-
aucet		***	\$		 	
7 - 17 - 17 - 17 - 17 - 17 - 17 - 17 -			\$	MI	0	
A de la	·					_
Freight, Other Delivery Charges	i		1 \$		0	

- 1- 1-1 - 4-1-1-24-24-24-24-24-24-24-24-24-24-24-24-24-	
TOTAL MATERIAL	\$ 306.82
TOTAL EQUIPMENT[\$
TOTAL JOURNEYMAN HOURS	0

•

Detail

Company: AJ Demor & Sons, Inc.
JohName: Pivik Elementary School COR #010 [Relocation of two (2) wall hydrants]
Material Set: Change Ord
Labor Set: Factor #1 (MCAA)
Run Date: 11-28-2011 @ 10:40:47
Sort Key: By Matl Group

Mati Group	Qty	Size	Description	1	Jnit rice	Price Total
Copper Tube L Small Copper Tube L Small	40 40	¾ (SUBTOTAL)	Type L Hard Copper Tube	\$	2.75	\$ 109.80 \$ 109.80
Hanger Galv Insulation Shields Hanger Galv Insulation Shields	9 9	3×12 (SUBTOTAL)	Galv Insulation Prot Shield	\$	3.34	\$ 30.06 \$ 30.06
Hangers Hangers	9 9	3 (SUBTOTAL)	Electro-Plated Std Clevis Hanger	\$ 1	11.44	\$ 102.96 \$ 102.9 6
Hangers Hangers	18 18	% (SUBTOTAL)	Hex Nuts	\$	80.0	\$ 1.51 \$ 1.51
Hangers	9 27 9	% % %	Elec-Plat Stl C-Clamp w/Locknut Galv Plated All Thread Rod C-Clamp w/Clevis	\$ \$	4.24 0.08 ~	\$ 38.16 \$ 2.16 \$ -
Hangers	45	(SUBTOTAL)				\$ 40.32
Miscellaneous Miscellaneous	2 18 6 25	% % % (SUBTOTAL)	Plastic Wrap Pipe Markers Plain Washer Ridgld ProPress Joint	\$ \$	7,00 0.03 "	\$ 14.00 \$ 0.54 \$ - \$ 14.54
Ridgid ProPress Copper Fitting Ridgid ProPress Copper Fitting	3	¾ (SUBTOTAL)	Ridgid ProPress Coupling	\$	2.54	\$ 7.62 \$ 7.62
	150	(TOTAL)				\$306.82

ภัก Fusco

from: Sent:

To: Cc: Subject:

Attachments:

converge@projectxnet.com

Monday, October 31, 2011 12:00 AM

Sandy Chlocchic; John Fusco; George Kieszek; Stevan Mracna; Steve Peterman

Mae Johnson; Dennis Russo; Steve Ackerman

RFI Closed - 073

MCMS_Notification_RFIDetailed.pdf

RFI Closed



Massaro

The following RFI has been closed.



To view additional details about this RFI, you may open the attached PDF.



To view the full RFI form in the Prolog Converge Web Client, click here.

Project:

Pium Borough SD - Pivik Elementary .

RFI Number:

073

/\FI Subject:

Frost Free Hose bibs

In review of the freeze-proof wall hydrant locations shown on the plumbing drawings, there are some indicated where piping drops down and will be exposed along wall (For example rooms B112 & D 108) and others dropping inside columns (for example Rooms A 104, D 104 &

C125).

RFI Question:

Highly do not recommend installing waterlines inside columns because of

the potential for freezing.

Please review freeze-proof wall hydrant locations and confirm locations as

to where they are to be installed.

RFI Answer:

The contractor needs to move the hose blbs for the space inside the columns to in the chase wall.

In room A 112 the contractor needs to relocate the hose bib in the chase

wall at column J&19.

In room A 108 the contractor needs to relocate the hose bib in the chase wall at column V&19.

1



Spec section 220700 3.13 calls for the domestic cold water to be insulated